



Product Change Notice

PCN Number: 13-1146-02-1
Issue Date: 29-AUGUST-2014

Exar Corporation
www.exar.com | Support: customersupport@exar.com

PRODUCTS AFFECTED:	SPX3819M5-L	SPX3819M5-L/TR
	SPX3819M5-L-3-3	SPX3819M5-L-3-3/TR
	SPX3819M5-L-5-0	SPX3819M5-L-5-0/TR

CHANGE CATEGORY:

<input type="checkbox"/> Material	<input type="checkbox"/> Process	<input type="checkbox"/> Package
<input type="checkbox"/> Design	<input type="checkbox"/> Datasheet	<input checked="" type="checkbox"/> Packing/Shipping
<input checked="" type="checkbox"/> Other: Alternate Assembly Site		

DESCRIPTION OF CHANGE:

1. Addition of an alternate qualified location, JCET, for assembly using copper wire or gold wire bonding.
2. Standard reel quantity will change from 2500 pieces to 3000 pieces.

IMPACT OF CHANGE:

There is no change to product form, fit or function.

TARGET IMPLEMENTATION DATE: 28-NOVEMBER-2014

Please contact customer support (customersupport@exar.com) for sample date availability or qualification data

PROPRIETARY INFORMATION
THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.