



# Product Change Notice

PCN Number: 16-0937-03  
Issue Date: 22-DECEMBER-2016

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:**

SP3220EBCA-L/TR	SP3220EBCY-L	SP3220EBCY-L/TR	SP3220EBEA-L
SP3220EBEA-L/TR	SP3220EBEY-L	SP3220EBEY-L/TR	SP3220ECA-L
SP3220ECA-L/TR	SP3220ECY-L	SP3220ECY-L/TR	SP3220EEA-L
SP3220EEA-L/TR	SP3220EEY-L	SP3220EEY-L/TR	SP3221ECA-L
SP3221ECA-L/TR	SP3221ECY-L	SP3221ECY-L/TR	SP3221EEA-L
SP3221EEA-L/TR	SP3221EEY-L	SP3221EEY-L/TR	

**CHANGE CATEGORY:**

<input type="checkbox"/> Material	<input checked="" type="checkbox"/> Process	<input type="checkbox"/> Package
<input type="checkbox"/> Design	<input type="checkbox"/> Datasheet	<input type="checkbox"/> Packing/Shipping
<input checked="" type="checkbox"/> Other: Alternate Foundry		

**DESCRIPTION OF CHANGE:**

Qualification of TSMC foundry for 0.25um HV20 process.

**IMPACT OF CHANGE:**

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 22-MARCH-2017

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.