



# Product Change Notice

PCN Number: 13-0730-02  
Issue Date: 16-SEPTEMBER-2013

## Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

### PRODUCTS AFFECTED:

SP3232EEN-L	SP3232EEN-L/TR	SP3232ECN-L	SP3232ECN-L/TR
SP3232EEY-L	SP3232EEY-L/TR	SP3232ECY-L	SP3232ECY-L/TR
SP3232EBEN-L	SP3232EBEN-L/TR	SP3232EBCN-L	SP3232EBCN-L/TR
SP3232EBEY-L	SP3232EBEY-L/TR	SP3232EBCY-L	SP3232EBCY-L/TR

### CHANGE CATEGORY:

<input type="checkbox"/> Material	<input checked="" type="checkbox"/> Process	<input type="checkbox"/> Package
<input type="checkbox"/> Design	<input type="checkbox"/> Datasheet	<input type="checkbox"/> Packing/Shipping
<input checked="" type="checkbox"/> Other: Alternate Foundry Site		

### DESCRIPTION OF CHANGE:

Qualification of an alternate foundry TSMC using 0.25um CMOS process.

### IMPACT OF CHANGE:

There is no change to product form, fit or function.

### TARGET IMPLEMENTATION DATE: 16-DECEMBER-2013

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

#### PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.